



Intel® PROSet/Wireless for Bluetooth Technology Software

Intel PROSet/Wireless BT Software v18.10 PV HF Release
Intel Wireless-AC 8260 (Snowfield Peak) Release for Win10

BT Driver: AHBTW0368_18.1.1527.1551

Ww28, 2015

Releases Overview

Intel is announcing the **18.10 PV** release of the Intel® PROSet/Wireless Bluetooth for Windows 10 on Snowfield Peak 8260.

Only the Snowfield Peak SRA, Supplemental QS/C0, QS/C0, and ES3/B2 adapters are supported in this release.

- Previously released pre-ES/A0, ES/K0, and ES2/B0 hardware versions are not supported.
 - By design, BT SW will present a Yellow Bang in Device Manager if executed over preES/A0, ES/K0, or ES2/B0 hardware. This to preclude wasted validation effort and issues worked/submitted because of using incorrect HW. So if a YB encountered, check for correct HW first.

Support for Windows 10 only

For validation guidance see the recommended BT validation guidance and software/hardware status slides below.

Announcing the release of the BT PV Software for Windows 10 on Snowfield Peak

General Information

- **BT Software Build**

- TIC # AHBTW0368_18.1.1527.1551
- Driver Version# 18.1.1527.1551

- **Supported Hardware**

- Snowfield Peak / 8260
 - SRA, Supplemental QS/C0, QS/C0
 - M.2 2230 MS and 1216
 - Previously released pre-ES/A0, ES/K0, and ES2/B0 hardware are not supported by this software release

- **Supported Operating Systems**

- Windows 10 - 64 bit
- Tested with Win10 version 10143

- **Tested Platforms**

- Skylake
 - SKL-Y ULX / SKL-U ULT / SKL-S DT / SKL-H Halo

Important Note

In this PV release, the SfP BT controller now complies with BT4.2. In the previous release the compliance level was at BT 4.1.

Shutdown /p no longer required if installing new driver over a previous one

Known Issues

Internal Defect D	Title	Status/Impact/Exposure/Frequency
MWG100235698	8260 BT cannot complete file transferred and audio file played at the same time.	Under investigation – seen on 1 headset
MWG100237380	Adverse behavior with HFP and HOGP.	Mouse can appear laggy after 10+ minutes while streaming music (e.g.)

Corrected Issues

ID	Description
MWG100236789	COEX defect fix
MWG100236571	Shutdown /p before installing new TIC# over current installation

Legal Disclaimer

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

All products, dates, and figures specified are preliminary based on current expectations, and subject to change w/o notice. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel, processors, chipsets, and desktop boards may contain design defects or errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Any code names featured are used internally within Intel to identify products that are in development and not yet publicly announced for release. Customers, licensees and other third parties are not authorized by Intel to use code names in advertising, promotion or marketing of any product or services and any such use of Intel's internal code names is at the sole risk of the user.

Intel product plans in this presentation do not constitute Intel plan of record product roadmaps. Please contact your Intel representative to obtain Intel's current plan of record product roadmaps.

Software and workloads used in performance tests may have been optimized for performance only on Intel microprocessors. Performance tests, such as SYSmark and MobileMark, are measured using specific computer systems, components, software, operations and functions. Any change to any of those factors may cause the results to vary. You should consult other information and performance tests to assist you in fully evaluating your contemplated purchases, including the performance of that product when combined with other products. For more information go to www.intel.com/performance

Results have been estimated based on internal Intel analysis and are provided for informational purposes only. Any difference in system hardware or software design or configuration may affect actual performance.

Intel does not control or audit the design or implementation of third party benchmark data or Web sites referenced in this document. Intel encourages all of its customers to visit the referenced Web sites or others where similar performance benchmark data are reported and confirm whether the referenced benchmark data are accurate and reflect performance of systems available for purchase.

References to 802.11n and 802.11ac performance are based on theoretical bandwidth maximums enabled by various 802.11n and 802.11ac specifications. Actual throughput will vary on your specific device operating system, hardware, software configurations, Internet connection speed and environmental conditions.

Intel® Wireless Display requires an Intel® Wireless Display enabled PC, tablet, or smartphone, a compatible adapter, and a TV. 1080p and Blu-Ray* or other protected content playback only available on select Intel® processors with built-in visuals enabled. Consult your PC manufacturer. For more information, see www.intel.com/go/widi

Intel® vPro™ Technology is sophisticated and requires setup and activation. Availability of features and results will depend upon the setup and configuration of your hardware, software and IT environment. To learn more visit: <http://www.intel.com/technology/vpro>

Intel® Active Management Technology requires activation and a system with a corporate network connection, an Intel® AMT-enabled chipset, network hardware and software. For notebooks, Intel® AMT may be unavailable or limited over a host OS-based VPN, when connecting wirelessly, on battery power, sleeping, hibernating or powered off. Results dependent upon hardware, setup and configuration. For more information, visit [Intel® Active Management Technology](#).

Intel Dual Band Wireless-AC 8260, Intel Dual Band Wireless-AC 3165, Intel Dual Band Wireless-AC 7265. Intel Dual Band Wireless-N 7265, Intel Wireless-N 7265, Intel Dual Band Wireless-AC 7260. Intel Dual Band Wireless-N 7260, Intel Wireless-N 7260, Intel Dual Band Wireless-AC 3160, Intel Smart Connect Technology, Intel Wireless Display, Intel vPro Technology, Intel Active Management Technology, Intel PROSet/Wireless Software, Intel PROSet/Wireless Software for Bluetooth Technology, Location Based Service, Intel Remote Wake Technology, Intel, Intel Inside, the Intel logo, Intel Core, Intel, Intel logo are trademarks of Intel Corporation in the United States and other countries.

This document contains information on products in the design phase of development.

*Other names and brands may be claimed as the property of others.

Copyright © 2015 Intel Corporation, All Rights Reserved

