



Intel® Bluetooth (BT) Software

Installation Guide

December 2017

Revision 1.2

Intel Confidential



Notice: This document contains information on products in the design phase of development. The information here is subject to change without notice. Do not finalize a design with this information.

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

Intel software products are copyrighted by and shall remain the property of Intel Corporation. Use, duplication, or disclosure is subject to restrictions stated in Intel's Software License Agreement, or in the case of software delivered to the government, in accordance with the software license agreement as defined in FAR 52.227-7013.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

The code names presented in this document are only for use by Intel to identify products, technologies, or services in development that have not been made commercially available to the public, i.e., announced, launched, or shipped. They are not "commercial" names for products or services and are not intended to function as trademarks.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an order number and are referenced in this document, or other Intel literature may be obtained by calling 1-800-548-4725 or by visiting Intel's website at <http://www.intel.com/design/literature.htm>.

Intel processor numbers are not a measure of performance. Processor numbers differentiate features within each processor family, not across different processor families. See http://www.intel.com/products/processor_number for details.

Intel is a trademark of Intel Corporation or in the US and other countries.

* Other brands and names may be claimed as the property of others.

Copyright © 2017 Intel Corporation. All rights reserved.



Contents

1	Introduction	6
2	Installation Methods.....	7
2.1	Command line options.....	7
2.1.1	Custom command line install properties.....	7
2.1.2	Command line examples for installation (msiexec and setup)	8
2.2	Installing Specialized BT Packages.....	8
	Intel Bluetooth OEM Tools.msi.....	9
2.3	Upgrading Driver Packages	9
2.4	Repairing Driver Packages	9
3	Appendix A: Setup.exe Return codes	10
4	Appendix B: MsiExe.exe Return Codes	11



Tables

Table 2-1	Command line install properties.....	7
Table 3-1	Setup.exe return codes	10



Revision History

Revision	Description	Date
1.0	Initial release	December 2015
1.1	More detail added	February 2016
1.2	Minor updates	December 2017

§



1 Introduction

The purpose of this document is to provide guidance to customers on installing/uninstalling/repairing the Intel® Bluetooth* (BT) software drivers.

The Intel® Bluetooth installer is very simple. The MSFT MSI installer framework provides further flexibility via install command line options and properties.

This document applies to all recent Intel WLAN modules (Wilkins Peak, Stone Peak, and Snowfield Peak) and to Microsoft*Windows* 7, 8.1, and 10.

The target audience for this document are direct customers (OEMs/ODMs).

This document is relevant for command line installations (setup.exe, autorun.exe, and msixec) as this is understood to be the customer preference.





2 Installation Methods

There are four different methods for installing (autorun, setup, .msi, and .inf):

- **Autorun.exe**
Autorun will detect the OS\bitness version, and launch the appropriate setup.exe to begin the application installation. Since autorun.exe calls on the appropriate setup.exe to execute the actual installation, this document mentions setup.exe with the assumption that the user understands that autorun.exe can also be used.
- **Setup.exe**
Setup.exe is a bootstrap application which sits in front of the .MSI. Setup.exe will read the configuration file and perform system checks. In general setup.exe takes the same arguments as msixec. Exceptions are pointed out below.
- **Microsoft Windows* installer package (.MSI)**
The Intel Bluetooth installer resides in an OS and bitness specific Microsoft Windows installer package. Each package contains all of the necessary files and logic to provide a full installation of the application and driver.
- **.INF file extension**
Windows 10 installation includes an INF folder. Driver software can be installed this way but there are no command line options. The defaults are used.

2.1 Command line options

Use of command line options is accepted by both the setup.exe and the msi. Parameters for their use fall within three categories in the Intel Bluetooth Installer (items in bold are default).

Command line switches passed on by Setup.exe to Microsoft Windows Installer - Setup will pass most of the other command lines it receives directly to the Windows Installer (e.g. /x, /qn, /qb, **/qf**, /L*v, etc.) see <https://msdn.microsoft.com/en-us/library/aa367988%28v=vs.85%29.aspx?f=255&MSPPErr=-2147217396> for more detail.

Standard properties interpreted by Microsoft Windows Installer (msiexec.exe) (REBOOT, ADDLOCAL, and ARPNOREMOVE). [https://msdn.microsoft.com/en-us/library/aa370905\(v=vs.85\).aspx](https://msdn.microsoft.com/en-us/library/aa370905(v=vs.85).aspx)

Custom properties that have a custom meaning for the product can be found in Section 2.1.1.

2.1.1 Custom command line install properties

Intel custom command line install properties and their default values are listed in Table 2-1. A description of each follows.

Table 2-1 Command line install properties

Argument	Value
SUPPORTREMOTEWAKEUP	Default is FALSE
LPUSBHUBWA	Only relevant for Windows 7, default is TRUE
SSDISABLE	Default is FALSE
BATTERY_LEVEL	Default value is 25; acceptable range is 0-100
IBTSIVA	Default is TRUE
FORCEDRIVERREMOVAL	Default is FALSE

Please note that the command line arguments are case sensitive.



Installation Methods

- **SUPPORTREMOTEWAKEUP**

Remote Wakeup allows the BT HID to wake up a platform that is in a sleep state.

- **LPUSBHUBWA**

This enables a work-around for a USB HUB issue seen on Windows 7/8.1 EHCI based platforms. If not enabled, the BT controller can get “stuck” in selective suspend state. Please see <http://support.microsoft.com/kb/2484742> for details.

- **SSDISABLE**

If set to TRUE, creates a SelectiveSuspendEnabled registry value. A reboot is required after installation for this to take effect.

- **BATTERY_LEVEL**

The minimum battery remaining percentage level at which an install or uninstall is allowed.

- **IBTSIVA**

IBTSIVA is a service that detects Yellow Bangs (YB) and forces a reset. This is frequently effective in removing Yellow Bangs.

Note: From 18.14 and 17.22 (WW46 releases), IBTSIVA cannot be disabled, that is, it is always TRUE.

- **FORCEDRIVERREMOVAL**

If this value is set to TRUE, it will remove the ibtusb.sys file from the folder Windows/System32/drivers on uninstall. Please note that this directory is controlled by Microsoft and Intel cannot guarantee that the cleanup will always work flawlessly.

2.1.2 Command line examples for installation (msiexec and setup)

Note: Autorun, setup or msiexec can be used for all examples.

/qn indicates quiet install – no popups.

- Take all the defaults and use USB interface
 - msiexec /i "Intel Bluetooth.msi" /qn
 - setup /qn (**Note:** /i does not apply to setup.exe or autorun)
 - autorun /qn
- Override defaults
 - msiexec /i "Intel Bluetooth.msi" /qn SUPPORTREMOTEWAKEUP=TRUE LPUSBHUBWA=FALSE
 - setup /qn SUPPORTREMOTEWAKEUP=TRUE LPUSBHUBWA=FALSE
- Set only SUPPORTREMOTEWAKEUP
 - msiexec /i "Intel Bluetooth.msi" /qn SUPPORTREMOTEWAKEUP=TRUE
 - setup /qn SUPPORTREMOTEWAKEUP=TRUE

2.2 Installing specialized BT packages

In addition to the main BT package, there is another, specialized BT package that is available with the BT release. This is the “Intel Bluetooth OEM Tools.msi” package.



Intel Bluetooth OEM Tools.msi

Installs the Intel Bluetooth OEM Tools.msi. These tools can be used for debugging and testing.

- To install the package:
`msiexec /i "Intel Bluetooth OEM Tools.msi" /qn`
- To un-install the existing installation (this will uninstall all features):
`msiexec /x "Intel Bluetooth OEM Tools.msi" /qn`

2.3 Upgrading driver packages

The common procedure for updating BT drivers is to uninstall an older release and then install the newer release. However, in some cases an older release can be upgraded.

For the upgrade procedure to work, the driver being upgraded must be a major driver version change. This is a Microsoft restriction. Please see <https://msdn.microsoft.com/en-us/library/aa370859%28v=vs.85%29.aspx?f=255&MSPPErr=-2147217396>

A major driver package version change means that at least the third number must be different. Here is an example:

- Driver xx.x.xxxx.xxxx to xx.x.yyyy.xxxx will upgrade
- Driver xx.x.xxxx.xxxx to xx.x.xxxx.yyyy will *not* upgrade

If the above major version requirement is met, then the normal method is used to upgrade.

If the installation was done using the following command line:

```
msiexec /I "Intel Bluetooth.msi" /qn ADDLOCAL=USB SUPPORTREMOTEWAKEUP=TRUE
```

then run the following command to upgrade to a newer version:

```
msiexec /i "Intel Bluetooth.msi" /qn ADDLOCAL=USB SUPPORTREMOTEWAKEUP=TRUE
```

2.4 Repairing Driver Packages

Repairing a driver means that the driver is re-installed.

To repair the existing package, run the following command:

```
msiexec /fpecms <PackageName>
```

To repair regular driver package via command line, run:

```
msiexec /fpecms "Intel Bluetooth.msi"
```

To repair the Bluetooth OEM Tools.msi package via command line, run:

```
msiexec /fpecms "Intel Bluetooth OEM Tools.msi"
```





3 Appendix A: Setup.exe Return Codes

Table 3-1 Setup.exe return codes

Value	Description
0	Installation is successful
0x65 (101)	Error: Newer product found already installed. This message indicates there is already a greater version installed on the system.
0x66 (102)	Error: Unsupported product upgrade found. This message indicates there is a version on the system that is not supported to be upgraded from.
0x67 (103)	Error: Unsupported Operating System.
0x69 (105)	Error: Low battery level. This message indicates the system was running on battery power and it is not at least at the minimum level (indicated in the setup.xml) to safely proceed with the installation.
0x15E	Error: System has pending reboot. This message indicates the system needs a reboot before installing this package.
0x661 (1633)	Error: Bitness mismatch. This message indicates that the 32-bit install package is being run on a 64-bit system or the 64-bit install package is being run on a 32-bit system.
0xbc2 (3010)	A restart is required to complete the install. This message indicates success. This does not include installs where the ForceReboot action is run.





4 Appendix B: MsiExe.exe Return Codes

Please refer to the MSFT link below:

[https://msdn.microsoft.com/en-us/library/aa376931\(v=vs.85\).aspx](https://msdn.microsoft.com/en-us/library/aa376931(v=vs.85).aspx)

